Work Orde May-13-13 1:02:	r ID 101461		*101	461*				•			Page 1
Revision ID: Item Name: F	D3195-5 Pad 5/13/13 Start Qty: 6-	14 *C*	Accept	*N900		100) *	Setup	Start Stop	177	S1* S2*
Required Date: 5 Reference:		\ ,		Cust Item I Customer:	D:						
Approvals:	Process Plan: MUS	Date: 13-05-	/ 6 Tooling:	Da	ate:	· -		Run	Start	*N	R1*
	QC:	•			ate:				Stop	*N	R2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qt	ject y	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr										
D3195	Rev B										_
100 *100* Small Fab	Small Fab		0.00				14		Ø		13-05-
Small Fab 110 *110* QC Quality Control		Punch as per Dwg D3195 completeness to step on W/O	0.00 3 5	9			14				
120 *120* Packaging	Identify as per dwg	g & Stock Location: <u>GA</u>	0.00	•	6	1	14x	- 4	<u> </u>	_/3-	06-30

Packaging

NCD.	Voc	1	No
NCR:	Yes	/	No

DQA:

Date:

NCR: Y	es / No				WORK ORDER NON-	-CONI	FORN	MANCE / UP	DATE			
								<u>-</u>		QA Closed:	Date	:
Work Orde	ŕ:		•		DISPOSITION				AGAINST D	EPARTMENT,	/PROCESS	
Part N					Rework Scrap		N	Skid-tube Machining	Crosstube Small Fab		Water Jet d. Eng. Coor.	Engineering Quality
NCR N	o				Use-as-is Work Order Update	∃		oforming Large Fab	Finishing Composite	Rec/Sto	re/Packaging Supplier	Other
Root				Descri	iption of work order update	Ini	itial	Act	tion	Sign &		1
Cause	Date	Step	Qty		or Non-conformance	Chie	f Eng	Desc	ription	Date	Verification	QC Inspector
oc/Data	_	1		ı								
quip/Tooling	_	1										
perator	_											
/laterial	4	1										
etup	_	}										
Other	_	İ										
rocess	_											
upplier	_											
raining												
Inapproved												
						FAULT	CATEC	GORY				
Landin	g Gear				General				_		_	_
L	Bending				Bend	ЩG	irain			Ovalized	<u> </u>	Pressure/Forced
	Centre N	ot Conce	ntric to (o/s	BOM/Route	Щн	lardwar	re		Over/Under	tolerance	Temperature/Cure
	Cracks				Broken/Damaged	lin	ıspecti	on Incomplete		Part Incorred	t _	Weld
	Crushed,	/Crimped			Burrs	In	ıstructi	ons Incomplete/l	Jnclear	Part Lost/Mi	ssing	Wrong Stock Pulled
	Cuffs				Contamination	\N	/lainte	nance		Part Moved		
	Heat Tre	at			Countersink		/lislabel	led		Positioned V	/rong	_
	Inspection	on Strip in	Tube		Cut Too Short	<u></u>	1isread			Power Loss/	Surge	Other
	Ripples i	n Bend			Drill Holes	o	ffset					
	Torque V	Vaves in (xtrusion	n [Drawing	. 0	ut of C	alibration				
	Turning :	Sequence			Finish	o	ut of S	equence				
	Wave/Tu	vist in Tul	эе	Γ	Folio	По	utside	Dimensions				

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Orde <i>May-13-13 1:02</i>		01461	*101461*								Page 2	
Item ID: Revision ID: Item Name: Start Date: Required Date:	D3195-5 Pad 5/13/13 5/31/13	Start Qty: 6.00 Req'd Qty: 6.00	*6* *6*	Accept	*N900 Cust Item II Customer:		100)*	Setup	Start Stop	*NS1* *NS2*	
Reference:	Process P		Date:	Tooling: SPC (Y/N):	Da	-		Run	Start	"INK I"		
	QC:		Date:			ite:				Stop	*NR2	
Sequence ID/ Work Center II 130 *130* QC Quality Control	D	Operation Description QC21- Final Inspection Memo	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Rej. Qty		Reject Insp. Number Stamp	, 9 30

								DQA:	Date:	٠.
NCR: Yes	/ No			_	WORK ORDER NON-O	CONFOR	MANCE / UPDATE	QA Closed:	Date:	
Work Order:					DISPOSITION			EPARTMENT	_	
Part No.					Rework Scrap Use-as-is	4 1	Skid-tube Crosstube Machining Small Fab noforming Finishing		Water Jet od. Eng. Coor. re/Packaging	Engineering Quality Other
NCR No.					Work Order Update	linein	Large Fab Composite		Supplier	Other
Root				Descri	ption of work order update	Initial	Action	Sign &		
Cause	Date	Step	Qty	(or Non-conformance	Chief Eng	Description	Date	Verification	QC Inspec
Doc/Data										
Equip/Tooling										
Operator		ļ								
Material										
Setup		1								•
Other										

QC Inspector

Landing Gear General Bend Ovalized Pressure/Forced Bending Grain Centre Not Concentric to O/S BOM/Route Over/Under tolerance Temperature/Cure Hardware Weld Cracks Broken/Damaged Inspection Incomplete Part Incorrect Burrs Wrong Stock Pulled Crushed/Crimped Instructions Incomplete/Unclear Part Lost/Missing Cuffs Maintenance Part Moved Contamination Mislabeled Positioned Wrong Countersink Heat Treat Other Power Loss/Surge Inspection Strip in Tube Cut Too Short Misread Drill Holes Offset Ripples in Bend Torque Waves in Extrusion Drawing Out of Calibration Out of Sequence Turning Sequence Finish

Outside Dimensions

FAULT CATEGORY

Wave/Twist in Tube

Folio

Process Supplier Training Unapproved

Picklist Print

May-13-13 1:02:11 PM

Page 1

Work Order ID:

101461

Parent Item:

D3195-5

Parent Item Name:

Pad

Start Date: 5/13/13

Required Date: 5/31/13

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev:A

New Issue 05-12-05 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3195		Manufactured	No			100	sf	100.6000	0.0094	0.0593682			
60 Durometer Neoprene R	ubber 1/8" thick								c1886 - Held.	Mar		<u>b_t(</u>	3-05-29
				Location		Loc Oty	<u>L</u> c	oc Code					/

LocationLoc OtvMAT052100.6421220.694672100

0.1316

NCR: Y	/es	/ No			·	WORK ORDER NON-C	10:	VFORM	MANCE / UPDA	NTE			
											QA Closed:	Date:	
Work Orde	٠					DISPOSITION				AGAINST DE	PARTMENT	PROCESS	
Part N	- lo					Rework Scrap Use-as-is Work Order Update		Therm	Machining noforming	Crosstube Small Fab Finishing Composite		Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other
Root Cause		Date	Step	Qty		tion of work order update or Non-conformance	ı	Initial nief Eng	Action Descript		Sign & Date	Verification	QC Inspector
Doc/Data	\Box												·
Equip/Tooling													
Operator		l.											
Material													
Setup													
Other											•		
Process				İ						_			
Supplier			,						·				
Training													
Unapproved		<u> </u>											
							AUL	T CATE	GORY				
Landi	$\overline{}$					General	_	1			ا با سا	Γ_]_ (
	$\overline{}$	Bending	_			Bend		Grain		<u> </u>	Ovalized	<u> </u>	Pressure/Forced
	-	Centre No	ot Concei	ntric to	o/s	BOM/Route	┝	Hardwa		<u> </u>	Over/Under		Temperature/Cure Weld
	-	Cracks		**		Broken/Damaged	⊢	4	on Incomplete		Part Incorred		Wrong Stock Pulled
	_	Crushed/	Crimped		<u> </u>	Burrs	┝	4	ions Incomplete/Unc	lear	Part Lost/Mi Part Moved	ssing	Wrong Stock Pulled
	\vdash	Cuffs			-	Countarial	\vdash	Mainte Mislabe		-	Positioned W	drong.	
	\vdash	Heat Trea		Tubo	\vdash	Countersink Cut Too Short	\vdash	Misread			Power Loss/		Other
	\vdash	Inspection Ripples in		odui	-	Drill Holes	\vdash	Offset	ı	<u></u>	r OWEL LOSS/.	ourge [Other
	\vdash	Torque W		vtrucio	<u> </u>	Drawing	\vdash	-	Calibration			·	· · · · · · · · · · · · · · · · · · ·
		rorque W	raves III t	. XLI USIO	''	Triaming	L	ا مور مر	ימייטי מנוטוו				. ,

Out of Sequence

Outside Dimensions

DQA:


Date:

Turning Sequence

Wave/Twist in Tube

Finish

Folio



ITEM	QTY -041	P/N	DESCRIPTION
	Х	D3195-041	BRACKET
1	1	D3195-1	BRACKET
2	1	D3195-5	PAD

ITEM	-043	P/N	DESCRIPTION
	Х	D3195-043	BRACKET
1	1	D3195-3	BRACKET
2	1	D3195-7	PAD

В	- ADDE - D3195 (B6-3.		S FORMAT. EET 1. DIMENSIONS EXTENSIVELY REVISED	RP	12.04.13		
Α	NEW IS	SUE		CP	03.06.23		
REV.			DESCRIPTION	BY	DATE		
DESIG	N	RP	DART AEROSP	ACE L	TD		
DRAW	N	RP	HAWKESBURY, ONTAF		1		
CHECH	ŒD	A.P.	DRAWING NO.		REV. B		
MFG. A	PPR.	BA	D3195		SHEET 1 OF 3		
APPRO	VED	W	TITLE		SCALE		
DE API	PR.	di.	BRACKET		NTS		
DATE	12.0)4.13	COPYRIGHT © 2003 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFEDENTIAL, AND IS SUPPLED ON THE EXPRESS CONCITION THA MOT TO BE LISED FOR ANY PURPOSE OF COMED ON COMMANDIATED TO ANY OTHER PRESON WITH AND TO BE LISED FOR ANY PURPOSE OF COMED ON COMPANY OF THE PURPOSE ANY PURPOSE ANY PURPOSE ANY THE PURPOSE ANY				

